

VB400 26.2 Release Note

Compatible with VideoManager EX release version 26.2.07 or newer

V26.2

- VB400 Firmware

Changes since version V26.1

New Features

Issue ID	Feature name	Summary
VB400-2438	TLK110 to VB400 connection (VB400)	The VB400 body worn camera can now connect to the TLK 110 WAVE PTX Radio when configured through Video Manager
VB400-2441	MOTOTRBO R5 Integration	The VB400 body worn camera can now connect to the R5 Mototrbo Radio when configured through Video Manager

Minor enhancements

Issue ID	Summary
VB400-2149	The X-100 external camera would fail to record or show LED lights after the VB400 was restarted or exited safety mode. In this case, only the VB400 body camera was capturing the footage. This issue has now been resolved.