

CLPe Firmware Release R02.10.02

Release Notes September 17th 2020

Fixes / Enhancements:	Firmware release R02.10.02 provides a patch to resolve the intermittent Auto Power off issue when using the CLP Series Multi Unit Charger model IXP4029B.
Applicable EMEA Models:	PMUE5510A - CLP446e 0.5W PMR446 EMEA PMUE5512A - CLP446e 0.5W PMR446 MULTIPACK EMEA PMUE5514A - CLPe PLUS UHF EMEA PMUE5516A - CLPe PLUS UHF MULTIPACK EMEA
Previous versions compatible with this update:	FW R02.10.00 CP R02.00.00 FW R02.10.00 CP R02.00.01 FW R02.10.01 CP R02.00.01