

MINITOR VI Firmware upgrade Kit R01.08

Customer Release Notes

For any questions, please contact Customer Resources at 1-800-927-2744.

I. Enhancements

None

II. Corrections

R01.08 upgrade kit resolves the slow speech of Male Voice Announcement when specific conditions are met.

Issue is observed when following conditions are met:

- Receive frequency programmed is a multiple of internal clock frequency 4.096MHz
- Battery is in a fully charged High Status
- Function switch announcements is programmed for "On & On Reset" or "On Reset Only"
- Male Voice announcement is selected, and
- When Monitor button is pressed

III. Known Issues

None